

BUND REFURBISHMENT

CONCRETE BUND, NORTHERN ENGLAND

The clients water cooling tower was leaking through the concrete base causing too much water to be lost which in turn created obvious problems with the system.



The containment area was grit-blasted to ensure a correctly prepared surface ready to receive the lining system was achieved.

A damaged areas within the containment area were repaired implementing resin concrete.

A GRP lining system was recommended for the project as the client required a long-term solution to this problem.

The lining system was applied to leave a strong, resilient system which has an easy clean ceramic like finish.



Please contact us on 08701 650900 for further information on our services.