

TANK REFURBISHMENT

WASTE WATER STORAGE TANK – POULTRY FACTORY

The waste water tank on this site was in very poor condition. There were numerous holes in the tank causing extensive leakage.



The tank was grit blasted to ensure all contaminants were removed and the correct profile was achieved to ensure optimum adherence of our lining system. Once all areas were grit blasted the tank was brushed and blown down and all debris and dust was removed.



The tank was primed and two layers of chopped strand mat were applied to the prepared and primed surface. A chemical resisting tissue veil was also applied to ensure a pinhole free lining system.

Once cured a resin wash was applied to all lined surfaces and again left to cure. This layer highlighted any surface irregularities which were sanded back to a smooth surface in readiness for the top coat.

The top coat was then applied to leave a smooth, durable and seamless finish.

This project was completed in four days and to the total satisfaction of the client. References can be supplied on this project.

Please contact us on 08701 650900 for further information on our services.